

Parts Replaced and Cost by Month

79171

1955 Chevrolet 3100

VIN: H55L001033

Parts Replaced in November 2008

Qty	Part Number	Description	Price Ea	Price Ext
1	SF-16	16oz Seafoam Motor Treatment	\$10.00	\$10.00
Parts Total for November 2008				\$10.00

Parts Replaced in December 2008

Qty	Part Number	Description	Price Ea	Price Ext
1	9015523	MAP / Pro Gas Cylinder 14 oz	\$9.98	\$9.98
1	DE 1613	Duplicolor Gloss Black Engine Enamel	\$5.69	\$5.69
Parts Total for December 2008				\$15.67

Parts Replaced in January 2009

Qty	Part Number	Description	Price Ea	Price Ext
0.5	1	Wash Wax All	\$9.95	\$4.98
Parts Total for January 2009				\$4.98

Parts Replaced in March 2009

Qty	Part Number	Description	Price Ea	Price Ext
6	3510	NGK B6S spark plug	\$0.00	\$0.00
Parts Total for March 2009				\$0.00

Parts Grand Total for your 1955 Chevrolet 3100	\$30.65
--	---------